

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	04/19/2018 04/19/2018	Zach Jojola

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_RD0827_01_s_2013_5				
Comment Code					
Inspector Comment					
RD 827 has a copy of the levee manuals.					

No Photos

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
DWR ID	DWR_RD0827_01_s_2013_7				
Comment Code					
Inspector Comment					
RD 827 shares a maintained stockpile of Flood Response Material with RD 785.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	04/19/2018 04/19/2018	Zach Jojola

LM Start		Rating **	A	Issue No.	9		
LM End		Issue Type +	Ma	Location *	N/A		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Flood Preparedness & Training				o		o
					o		o
DWR ID	DWR_RD0827_01_f_2014_9						
Comment Code							
Inspector Comment							
RD 827 works jointly with RD 785 on Flood Preparedness and Training.							

No Photos

LM Start	0.04	Rating **	A/W	Issue No.	6
LM End	0.04	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.674833 °	38.674833 °
				-121.630039 °	-121.630039 °
DWR ID	DWR_RD0827_01_s_2018_6				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Small rills beginning to form on waterside slope. Recommend monitoring.					

Photo 1 of 1 : SP_2018_RD0827_187_6_20180423_00016.jpg



View of rills on the waterside slope. Spring 2018.

LM Start	0.34	Rating **	A/W	Issue No.	17
LM End	0.34	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.671767 °	38.671767 °
				-121.626065 °	-121.626065 °
DWR ID	DWR_RD0827_01_f_2017_17				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Rill on waterside slope. Recommend monitoring.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	04/19/2018 04/19/2018	Zach Jojola

LM Start	0.45	Rating **	M	Issue No.	8	
LM End	0.45	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Encroachments			38.670638 °		38.670638 °
				-121.624652 °		-121.624652 °
DWR ID	DWR_RD0827_01_s_2018_8					
Comment Code						
TR : Tree or limb						
Inspector Comment						
Fallen tree on the waterside slope.						

No Photos

LM Start	0.51	Rating **	M	Issue No.	13
LM End	0.51	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.669929 °	38.669929 °
				-121.623776 °	-121.623776 °
DWR ID	DWR_RD0827_01_s_2016_13				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Rills caused by rain.					

Photo 1 of 2 : SP_2018_RD0827_187_13_20180306_00006.jpg



View of the erosion on the landward side of the levee looking downstream. Spring 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	04/19/2018 04/19/2018	Zach Jojola

LM Start	0.51	Rating **	M	Issue No.	13 (cont)	
LM End	0.51	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			38.669929 °		38.669929 °
				-121.623776 °		-121.623776 °
DWR ID	DWR_RD0827_01_s_2016_13					
Comment Code						
E2 : Schedule repair of erosion site prior to the next inspection.						
Inspector Comment						
Rills caused by rain.						

Photo 2 of 2 : SP_2018_RD0827_187_13_20180306_00007.jpg



Updated view of runoff erosion site. LS slope. Fall 2016.

LM Start	0.61	Rating **	A/W	Issue No.	22
LM End	0.92	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.668873 °	38.665750 °
				-121.622513 °	-121.618523 °
DWR ID	DWR_RD0827_01_s_2012_22				
Comment Code					
V8 : Environmental Requirements.					
Inspector Comment					

Photo 1 of 2 : SP_2018_RD0827_187_22_20180306_00010.jpg



Revegetation site spring 2012.

LM Start	0.61	Rating **	A/W	Issue No.	22 (cont)
LM End	0.92	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP_2018_RD0827_187_22_20180306_00011.jpg



View of the revegetation site on the waterward side of the levee looking downstream. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	04/19/2018 04/19/2018	Zach Jojola

LM Start	1.00	Rating **	M	Issue No.	15
LM End	1.01	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.664920 °	38.664720 °
				-121.617557 °	-121.617318 °
DWR ID	DWR_RD0827_01_s_2017_15				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Prunings and fallen tree limbs on waterside levee slope.					

No Photos

LM Start	1.12	Rating **	M	Issue No.	3
LM End	1.12	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.663542 °	38.663542 °
				-121.616056 °	-121.616056 °
DWR ID	DWR_RD0827_01_f_2016_3				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Erosion on the crown and waterside slope from runoff.					

Photo 1 of 3 : SP_2018_RD0827_187_3_20180306_00001.jpg



Updated view of erosion on waterside levee slope. Spring 2017.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	04/19/2018 04/19/2018	Zach Jojola

LM Start	1.12	Rating **	M	Issue No.	3 (cont)	
LM End	1.12	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start	End	
Item	Erosion / Bank Caving			38.663542 °	38.663542 °	
				-121.616056 °	-121.616056 °	
DWR ID	DWR_RD0827_01_f_2016_3					
Comment Code						
E2 : Schedule repair of erosion site prior to the next inspection.						
Inspector Comment						
Erosion on the crown and waterside slope from runoff.						

LM Start	1.12	Rating **	M	Issue No.	3 (cont)
LM End	1.12	Issue Type +	Ma	Location *	WS

Another view of erosion on levee slope. A hole on the waterside slope has widened due to runoff. Spring 2017.

16/31/2016

View of erosion on crown continuing to WS slope. Fall 2016.

LM Start	1.14	Rating **	A/W	Issue No.	14
LM End	1.14	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.663377 °	38.663377 °
				-121.615895 °	-121.615895 °
DWR ID	DWR_RD0827_01_s _ 2017_14				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Minor erosion on waterside slope. Recommend monitoring					

View of erosion on waterside levee slope. Spring 2017.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable	A : Acceptable N : Not Inspected/Rated	Ma : Maintenance Deficiency
WS : Water Side	M : Minimally Acceptable C : Corrected	Ob : Design & System Obsolescence
CR : Crown	U : Unacceptable A/W : Acceptable but Monitor & Maintain	En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	04/19/2018 04/19/2018	Zach Jojola

LM Start	1.21	Rating **	M	Issue No.	11
LM End	1.21	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.662546 °	38.662546 °
				-121.615083 °	-121.615083 °
DWR ID	DWR_RD0827_01_s_2017_11				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Fallen tree limbs on waterside levee slope.					

No Photos

LM Start	1.30	Rating **	M	Issue No.	4
LM End	1.30	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.661485 °	38.661485 °
				-121.614006 °	-121.614006 °
DWR ID	DWR_RD0827_01_s_2017_4				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Fallen tree limbs on waterside levee slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	04/17/2018 04/17/2018	Zach Jojola

LM Start	0.15	Rating **	A/W	Issue No.	10	
LM End	0.16	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			38.674778	°	38.674583
				-121.642806	°	-121.642722
DWR ID	DWR_RD0827_02_f_2017_10					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:200						
Site Designation:RD 827-02						
Repair Type: Erosion						
Rating:Area of Concern						
Field Date:6/6/2017						
Notes: no damage visible, ws armored with riprap						

Photo 1 of 3 : LEVAL_SP_2018_200_1239.jpg



LM Start	0.15	Rating **	A/W	Issue No.	10 (cont)
LM End	0.16	Issue Type +	Ma	Location *	

Photo 2 of 3 : LEVAL_SP_2018_200_1245.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	04/17/2018 04/17/2018	Zach Jojola

LM Start	0.15	Rating **	A/W	Issue No.	10 (cont)	
LM End	0.16	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			38.674778 °	38.674583 °	
				-121.642806 °	-121.642722 °	
DWR ID	DWR_RD0827_02_f_2017_10					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:200						
Site Designation:RD 827-02						
Repair Type: Erosion						
Rating:Area of Concern						
Field Date:6/6/2017						
Notes: no damage visible, ws armored with riprap						

Photo 3 of 3 : LEVAL_SP_2018_200_1246.jpg



LM Start	0.16	Rating **	C	Issue No.	12	
LM End	0.16	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			38.674523 °	38.674523 °	
				-121.642770 °	-121.642770 °	
DWR ID	DWR_RD0827_02_f_2017_12					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:201						
Site Designation:RD 827-03						
Repair Type: Erosion						
Rating:Critical						
Field Date:6/5/2017						
Notes:						

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	04/17/2018 04/17/2018	Zach Jojola

LM Start	0.16	Rating **	C	Issue No.	11
LM End	0.16	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.674523 °	38.674523 °
				-121.642767 °	-121.642767 °
DWR ID	DWR_RD0827_02_s_2017_11				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
100' section of sloughing on landside levee slope.					

No Photos

LM Start	2.62	Rating **	M	Issue No.	6
LM End	2.62	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.643375 °	38.643375 °
				-121.621776 °	-121.621776 °
DWR ID	DWR_RD0827_02_s_2018_6				
Comment Code					
DE : Debris					
Inspector Comment					
Fridge on the waterside slope.					

No Photos

LM Start	2.72	Rating **	A/W	Issue No.	14
LM End	2.74	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.642088 °	38.641817 °
				-121.620972 °	-121.620802 °
DWR ID	DWR_RD0827_02_s_2017_14				
Comment Code					
Inspector Comment					
Slope stability on landside levee slope near LMA pump.					

Photo 1 of 2 : SP_2018_RD0827_188_14_20180306_00013.jpg



View of erosion and visqueen on landside levee slope. Spring 2017.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	04/17/2018 04/17/2018	Zach Jojola

LM Start	2.72	Rating **	A/W	Issue No.	14 (cont)
LM End	2.74	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.642088 °	38.641817 °
				-121.620972 °	-121.620802 °
DWR ID	DWR_RD0827_02_s_2017_14				
Comment Code					
Inspector Comment					
Slope stability on landside levee slope near LMA pump.					

Photo 2 of 2 : SP_2018_RD0827_188_14_20180306_00014.jpg



Additional view of erosion on landside levee slope. Spring 2017.

LM Start	2.72	Rating **	M	Issue No.	13
LM End	2.73	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.642139 °	38.642028 °
				-121.620750 °	-121.620667 °
DWR ID	DWR_RD0827_02_f_2017_13				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:199					
Site Designation:RD 827-01					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:6/6/2017					
Notes: landside. Visqueen has dried up and is no longer protecting the slope.					

Photo 1 of 4 : SP_2018_RD0827_188_13_20180306_00009.jpg



Updated view of sloughing on landside slope. Fall 2017.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	04/17/2018 04/17/2018	Zach Jojola

LM Start	2.72	Rating **	M	Issue No.	13 (cont)	
LM End	2.73	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			38.642139 °	38.642028 °	
				-121.620750 °	-121.620667 °	
DWR ID	DWR_RD0827_02_f_2017_13					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:199						
Site Designation:RD 827-01						
Repair Type: Erosion						
Rating:Area of Concern						
Field Date:6/6/2017						
Notes: landside. Visqueen has dried up and is no longer protecting the slope.						

Photo 2 of 4 : LEVAL_SP_2018_199_1231.jpg



Photo 3 of 4 : LEVAL_SP_2018_199_1232.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	04/17/2018 04/17/2018	Zach Jojola

LM Start	2.75	Rating **	M	Issue No.	18 (cont)
LM End	2.75	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.641633 °	38.641633 °
				-121.620725 °	-121.620725 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:33032
DS_ID:21169
EP_NO: 5611
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Crossing appears to have been removed and replaced under maintenance back in 2008. No permit has been found--need to contact owner to obtain additional information about replacement.
FIELD_STRUCT_DESC: [RD No. 827 Pumping Plant] 22-inch (not 24-inch as mentioned in desk study) steel drainage pipe through the levee, 8 feet below the crown. Corrugated metal cutoff wall around pipe at center of levee. Siphon breaker on waterside (WS) slope. Flap gate on WS end. Pipe is exposed along WS slope. (portion of pipe was removed and replaced, from landside to waterside shoulder, under Permit No. 5611 (1968)). [Additional Reference(s): DWR Levee Logs, 2005. USACE Sacramento O&M Manual Unit No. 122 Part No. 1, August 1955, (Station 3+75)]
FS Date: 3/18/2014

LM Start	2.75	Rating **	M	Issue No.	18 (cont)
LM End	2.75	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_SP_2018_33032_59777.jpg



Pump station located on landward side.

Photo 3 of 3 : UCIP_SP_2018_33032_59776.jpg



Reminisce piles located on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---